ALTEC

- 1. At the start, it should find the installation path of the software automatically. If it fails this operation, the software will ask you the installation path of the AHU Selection Software;
- 2. Select the new license file license.cfg;
- 3. Click the button **Repair License**. After that, you can try to launch the AHU Selection Software.

ensekepair - Ounty		
File ?		
Installation path: Select the license file:	1	Browser
	Repair License	Close
ady		CAP NUM SCRL